

# 5910-A

# OPERATING INSTRUCTIONS

## SOILMOISTURE METER

AUGUST 2007



Depress red button to insert soilmoisture blocks leads

Insert leads in angled slot

Step 1


Depress "set button" and move "adjusting knob" until display reads 100.

Pushing up on knob lowers the reading. Pushing down on knob increases the reading.



Side View

For Battery Replacement remove 4 corner screws.



Back View

**SOILMOISTURE EQUIPMENT CORP.**

P.O. Box 30025, Santa Barbara, CA 93105 U.S.A.

Telephone 805-964-3525 - Fax No. 805-683-2189

Email: [sales@soilmoisture.com](mailto:sales@soilmoisture.com) - Website: <http://www.soilmoisture.com>

