

Aquaprobe PC-KIT




The new Aquaprobe PC-KIT allows you to calibrate and record measurements from an Aquaprobe without the need for a GPS Aquameter.



PC-KIT interface box

The Aquaprobe PC-KIT consists of the USB interface kit and the AquaCal PC application. The Aquaprobe cable is plugged into the interface box and the USB cable can be connected to your PC, once connected you can view live readings on the PC, calibrate all sensors of the Aquaprobe, perform cleaning cycles on an AP-7000 and even record measurements with data being recorded to a csv file.

- Easily calibrate every possible parameter
- Produce a detailed calibration certificate
- Green box signifies measurement stable
- Easily restore calibrations to factory default



AquaCal PC application screen

A) Set the Aux sensor assignment using the drop down menus

B) Extra information to assist in ISE calibration: Point 3 shows temperature (T) -10°C reminding that the temperature should be at least 10°C lower